

Preheaters Quick Start Guide


1. Introduction

Dear Customer! Thank you for your purchase in TME! To protect the environment we have prepared for you this quick start guide. Before operating the unit, please read it carefully. Please visit www.tme.eu Illustrations in this manual are only example images and may differ from the actual item. It does not change their main characteristics.

2. Application

The device is used to PCB heating before assembly and disassembly of electronic components.

3. Unit setup and operation



P - Heating plate
L - Temperature display
T - Temperature controller
W - Power on switch
O - Ventilation holes

- Place the device on a stable surface.
- Plug the power cord into the appropriate outlet.
- Place the PCB on the heater and if necessary connect the temperature probe to the PCB.
- Turn on the power.
- Set the desired temperature and wait until the warm up.

4. Precautions



Transfer Multisort Elektronik Sp. z o.o.

ul. Ustronna 41, 93-350 Łódź, Poland, correspondence address: 90-951 Łódź 40, PO BOX 2071
tel. +48 42 645 54 44, fax +48 42 645 54 70, export@tme.eu, www.tme.eu

VAT ID: PL7290108984, REGON (NACE): 473171710, District Court for Łódź-Śródmieście, NCR: 0000165815, initial capital: 3 300 000 PLN

- Do not turn on the unit immediately after moving it from a cold to a warm room. Condensation may damage the device.
- Damaged power cord must be immediately replaced by a qualified technician.
- The device can be used only in well-ventilated areas.
- Do not cover the ventilation holes.
- Never operate the unit with wet hands or when wires are wet as this could cause a short circuit or electric shock.
- Do not place hot device near the flammable objects, liquids or gases.
- Do not use the device to heat the plastic as it can produce toxic fumes.
- There is a risk of burns from touching of the heated area.
- Use the proper protective clothing.
- Do not work on live parts.
- Do not leave the unit unattended.
- The unit should be kept out of reach of children.
- Do not use the preheater for purposes other than PCB heating.
- After finishing work, turn off the power, unplug the power cord and wait until the device cools down.
- It is forbidden to make any construction modifications to the device. Unauthorised construction modifications will result in loss of warranty, and may also cause a malfunction or an accident.
- Never use the device as a hair dryer, touch the heating element or direct hot air directly onto the skin.
- Worn electrical equipment can not be disposed of with othe household waste. Worn electrical equipment must be stored in places designated for that.



Transfer Multisort Elektronik Sp. z o.o.

ul. Ustronna 41, 93-350 Łódź, Poland, correspondence address: 90-951 Łódź 40, PO BOX 2071
tel. +48 42 645 54 44, fax +48 42 645 54 70, export@tme.eu, www.tme.eu

VAT ID: PL7290108984, REGON (NACE): 473171710, District Court for Łódź-Śródmieście, NCR: 0000165815, initial capital: 3 300 000 PLN